

Mixing ratio (By weight)

Epoxy primer	G-5900	20.0 kg container can
Hardener	H-5900	5.0 kg container can

Mix well (2 – 3) minutes and apply immediately .

Application

Brushing. rolling, spraying, airless spraying .

Surface preparation

Maintenance: Remove oil and grease ect. thoroughly with suitable detergent.
Remove salts and other contaminants by high pressure fresh water cleaning.

Preceding & Follow-up Coating

Epoxy system :

- 1- Epoxy primer (G-5900)
- 2- top coat finish (D-5544 SFFA) or (D-5900 A)

Application conditions

Use only where application and curing can proceed at temperature above 5°C, and below 45°C in the shadow. The temperature of the surface must be also be above these limits .The Relative Humidity must not exceed 80% .

Stirring

Stir the base thoroughly in order to redisperse any possible settling after storage.
After mixing it is equally important to maintain stirring to keep the wet paint as a homogeneous mixture.

Packaging

weight of container		(kilogram)
Epoxy primer	G-5900	20
Hardener	H-5900	5